


INE-W967HD navigation software update procedure



Update procedure

The INE-W967HD can be updated via USB connection (see connection diagram below). Before starting to update, please check following notes. The download file is compressed in zip format. The contents of the download need to be extracted to a freshly formatted USB memory (FAT32).


Update file contents / storage place



Notes

- Do NOT use the compressed file for update, otherwise the INE-W967HD cannot recognize the files.
- Do NOT change folder name and file names, otherwise the INE-W967HD cannot recognize the files.
- Do NOT store any other folders/files on the USB memory.
- Do NOT remove the USB memory while updating.
- Do NOT update while driving.
- Do NOT press any buttons while updating.
- Do NOT turn off vehicle's ignition or head unit's power switch while updating.
Some modern vehicles may shut down the ignition (ACC) if the engine is not running for some time.
If you are not sure if this applies to your car, leave the engine running while the update is in progress.
- Certain manufacturer's USB memory may not work. If so, try a different manufacturer's USB memory.


Connection



Install update software

- 1 Store the downloaded folders "LIMOBSP", "LIMONAVI" and "LIMOAUTORUN.exe" to the Root Directory of an empty USB memory.

- 2 Please select "Ok" in Language Sel. Screen.




- 3 Please press "NAVI" hardkey on face plate to recall the navigation screen.




- 4 Connect the USB memory to the USB connector of the INE-W967HD.
※Update will start automatically.
※Update will be completed in 90 seconds.

- 5 After completing the update, please remove the USB memory stick.



※When the update is finished, the INE-W967HD will reset and automatically reboot.

- 6 Check the navigation software version by pressing the "NAVI" hardkey to open the navigation menu → Information → About → Version information: 9.18.31.652346




X108U navigation software update procedure



Update procedure

The X108U can be updated via USB connection (see connection diagram below). Before starting to update, please check following notes. The download file is compressed in zip format. The contents of the download need to be extracted to a freshly formatted USB memory (FAT32).


Update file contents / storage place



Notes


- Do NOT use the compressed file for update, otherwise the X108U cannot recognize the files.
- Do NOT change folder name and file names, otherwise the X108U cannot recognize the files.
- Do NOT store any other folders/files on the USB memory.
- Do NOT remove the USB memory while updating.
- Do NOT update while driving.
- Do NOT press any buttons while updating.
- Do NOT turn off vehicle's ignition or head unit's power switch while updating.
Some modern vehicles may shut down the ignition (ACC) if the engine is not running for some time.
If you are not sure if this applies to your car, leave the engine running while the update is in progress.
- Certain manufacturer's USB memory may not work. If so, try a different manufacturer's USB memory.

Connection



Install update software

- 1 Store the downloaded folders "LIMOBSP", "LIMONAVI" and "LIMO AUTORUN.exe" to the Root Directory of an empty USB memory.
- 2 Please select "Ok" in Language Sel. Screen.




- 3 Please press "NAVI" hardkey on face plate to recall the navigation screen.




- 4 Connect the USB memory to the USB connector of the X108U.
※Update will start automatically.
※Update will be completed in 90 seconds.

- 5 After completing the update, please remove the USB memory stick.



※When the update is finished, the X108U will reset and automatically reboot.

- 6 Check the navigation software version by pressing the "NAVI" hardkey to open the navigation menu → Information → About → Version information: 9.18.31.652346




X110 navigation software update procedure



Update procedure

The X110 can be updated via USB connection (see connection diagram below). Before starting to update, please check following notes. The download file is compressed in zip format. The contents of the download need to be extracted to a freshly formatted USB memory (FAT32).


Update file contents / storage place



Notes


- Do NOT use the compressed file for update, otherwise the X110 cannot recognize the files.
- Do NOT change folder name and file names, otherwise the X110 cannot recognize the files.
- Do NOT store any other folders/files on the USB memory.
- Do NOT remove the USB memory while updating.
- Do NOT update while driving.
- Do NOT press any buttons while updating.
- Do NOT turn off vehicle's ignition or head unit's power switch while updating.
Some modern vehicles may shut down the ignition (ACC) if the engine is not running for some time.
If you are not sure if this applies to your car, leave the engine running while the update is in progress.
- Certain manufacturer's USB memory may not work. If so, try a different manufacturer's USB memory.

Connection



Install update software

- 1 Store the downloaded folders "LIMOBSP", "LIMONAVI" and "LIMO AUTORUN.exe" to the Root Directory of an empty USB memory.
- 2 Please select "Ok" in Language Sel. Screen.



- 3 Please press "NAVI" hardkey on face plate to recall the navigation screen.



- 4 Connect the USB memory to the USB connector of the X110.
※Update will start automatically.
※Update will be completed in 90 seconds.

- 5 After completing the update, please remove the USB memory stick.



※When the update is finished, the X110 will reset and automatically reboot.

- 6 Check the navigation software version by pressing the "NAVI" hardkey to open the navigation menu → Information → About → Version information: 9.18.31.652346

