

## **i209-GM Firmware Update v5.100**

Rating: Unrated | Last Updated: Mon, Aug 5, 2019 at 6:58 PM

This firmware update corrects an issue where Samsung phones updated to Android version 9 continued to play the ring tone in the background during a call.

Please remember download both the update manual and update file.

Posted by: [Alpine KB](#) - Mon, Aug 5, 2019 at 6:58 PM. This article has been viewed 2814 times.

Online URL: </article/i209-gm-firmware-update-v5-100.html>