

## **iLX-F511, iLX-F509, i509-WRA-JK, i509-WRA-JL, iLX507 Firmware Update V 2.0.300**

Rating: 1/5 from 1 votes | Last Updated: Thu, Jan 19, 2023 at 10:41 PM

**This firmware update corrects issues with the following:**

- **Wired and wireless Apple CarPlay connectivity.**
- **Echo when making phone calls when using preouts for external amplifiers.**
- **Flickering camera screen when selecting camera from the AUX screen.**
- **Apple CarPlay disappears from the Function Select popup on the device list when the CarPlay connection is changed to another iPhone.**
- **RUX-HO2 connectivity with wireless CarPlay**
- **Adds Tidal support**
- **OEM SiriusXM integration added**
- **Auto Presets for FM tuner not showing the correct frequency**

**Please download both the update file and update manual.**

Posted by: [Alpine KB](#) - Fri, Jun 3, 2022 at 2:49 PM. This article has been viewed 23665 times.

Online URL: </article/ilx-f511-ilx-f509-i509-wra-jk-i509-wra-jl-ilx507-firmware-update-v-2-0-300.html>