

## **X009-RAM will not connect to iPhone**

Rating: Unrated | Last Updated: Sat, Oct 14, 2017 at 12:49 AM

Due to the length of the iPhone cable, there is an issue connecting the iPhone thru the OEM USB plug. In this case use the Alpine KCU-471i cable instead of the Apple iPhone cable.

Posted by: [Alpine KB](#) - Sat, Oct 14, 2017 at 12:49 AM. This article has been viewed 2111 times.

Online URL: </article/x009-ram-will-not-connect-to-iphone.html>